



OREGON ENGINE REBUILDERS

TECHNICAL BULLETIN

September 1994

TB 1149

Revised PCV Valve on Toyota 2.4L Engines

To help improve the effectiveness of the positive crankcase ventilation(PCV) system on Toyota 2.4L engines, a revised assembly is now available. The assembly has been installed on all engines built after build number 1574042. There is both a PCV valve material and rubber hose assembly change, which provides longer life and better sealing.

On this engine, an improperly operating PCV system has been the single most common cause of oil consumption. Any design improvement in this system should ultimately reduce the number of possible oil consumption related complaints. The revised PCV valve is available under Part #12204-35040 and the new hose assembly is Part #12261-35011.

The AERA Technical Committee

Portions of materials contained herein have been reprinted with permission of General Motors Corporation, Service Operations. This information is provided from the best available sources. However, AERA does not assume responsibility for data accuracy or consequences of its application. Members and others are not authorized to reproduce or distribute this material in any form, or issue it to their branches, divisions, or subsidiaries, etc. at a different location, without written permission. © Copyright AERA 2006